

8045.25

FR9B - FH120 - FH150

4 cil. 104.00 mm 3.908 c.c.

| Componente | oe | Ref. | I. | U. | Observaciones | Ref. Origen |
|---------------------|----|--------|----|----|-------------------------------------|-------------|
| 10 Cigüeñal | oe | 14051 | | 1 | | 504075031 |
| | | 17400 | | 1 | 2 Engranaje / | 98451528 |
| 11 Biela | | 41750 | | 4 | bulón 38 mm / 4780624 / Recta | 98461751 |
| 12 Tornillo biela | | 390420 | | 8 | | 4780627 |
| 14 Cojinete biela | oe | 160780 | | 4 | 63.72 Ø / ancho 28.70 mm / | 1930181 |
| 15 Cojinete bancada | oe | 165390 | | 5 | 79.71 Ø / ancho 24.99 mm / | 1930812 |
| 16 Cojinete axial | oe | 230030 | | 1 | 87.77 Ø / ancho 3.43 mm / | 1901385 |
| 20 Culata | | 109700 | | 1 | | 99452265 |
| 24 Tornillo Culata | | 480170 | | 18 | | 4796457 |
| 25 Taquet | | 220300 | | 8 | 14 mm / | 4693033 |
| | | 220330 | | 8 | 15 mm / | 98471524 |
| 40 Juntas | | 2040 | | 1 | Juntas Descarbonizar sin culata | |
| | | 3041 | | 1 | Juntas Motor sin culata sin retenes | |
| | | 1022 | | 1 | Junta de culata | |
| | | 6000 | | 1 | Junta de cárter | |
| | | 7002 | | 1 | Retén delantero 42x65x12 | |
| | | 8003 | | 1 | Retén trasero 125x150x15 | |
| 55 Bomba Aceite | | 142030 | | 1 | | 4813652 |
| 56 Turbo | oe | 660470 | | 1 | | 4817756 |
| 71 Motor Aligerado | | 80813 | | 1 | | 804525 |
| | | 80814 | | 1 | Variante 150 / | 804525 |